Appendix A: NO₂ Monitoring Data



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC40 Sawyers Way

Figure A1: DC40 Sawyers Way



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC42 Wood Lane End

Figure A2: DC42 Wood Lane End

LAQM Progress Report 2013



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC43 Roman Way Markyate

Figure A3: DC43 Roman Way, Markyate



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC46 High Street Bovingdon

Figure A4: DC46 High Street, Bovingdon



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC47 High Street Berkhamsted

Figure A5: DC47 High Street, Berkhamsted



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC48 Prince Edward Street Berkhamsted

Figure A6: DC48 Prince Edward Street, Berkhamsted



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC50, DC62, DC63, DC84, DC86, DC87 and DC88

Figure A7: NO₂ Diffusion Tubes within High Street Northchurch AQMA



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC51 Brook Street Tring

Figure A8: DC51 Brook Street, Tring



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC52 High Street Tring

Figure A9: DC52 High Street, Tring



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC53 Charles Street Tring


Figure A10: DC53 Charles Street, Tring

LAQM Progress Report 2013



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC54 Watford Road Kings Langley

Figure A11: DC54 Watford Road, Kings Langley



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC55 High Street Kings Langley

Figure A12: DC55 High Street, Kings Langley



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC57, DC64, DC65, DC69 and DC70

Figure A13: NO₂ Diffusion Tubes within (and in close proximity to) Lawn Lane, Hemel Hempstead AQMA



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC58 Gammon Close

Figure A14: DC58 Gammon Close



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC59 Wadley Close

Figure A15: DC59 Wadley Close



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC60 Field Road

Figure A16: DC60 Field Road



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC61 St Agnells Lane

Figure A17: DC61 St Agnells Lane



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC66, DC71, DC73, DC74 and DC85

Figure A18: NO_2 Diffusion Tubes located within (and in close proximity to) London Road, Apsley AQMA



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC67 Allandale

Figure A19: DC67 Allandale



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC68 Belswains Sappi

Figure A20: DC68 Belswains Sappi



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC75 The Meads

Figure A21: DC75 The Meads



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH




DC76, DC77, DC78 and DC79

Figure A22: NO₂ Diffusion Tubes located at Cotterells, Hemel Hempstead



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC81 Sappi 2

Figure A23: DC81 Sappi 2



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC83 Briar Way

Figure A24: DC83 Briar Way



Regulatory Services

Civic Centre, Marlowes Hemel Hempstead, Herts, HP1 1HH



DC89 High Street Markyate

Figure A25: DC89 High Street, Markyate